

NOTICE

MAINTENANCE WORK ON RESTACKING FREQUENCY EXERCISE

For information, there is maintenance work on frequency restacking exercise at Bukit Karatong transmitter station in Sabah from 0100 – 0600 hours on June 24, 2020.

The affected areas are as follows:

No	Location	Transmitter	Affected Areas
1	Sabah	Bukit Karatong	Kota Kinabalu

We urge you to put your decoders or integrated television (IDTV) on 'standby mode'.

If you encounter any interruption, kindly contact MYTV Customer Careline at 1800-18-1088 for assistance. We apologies for any inconvenience caused.

MYTV Customer Careline 1800-18-1088

www.mytvbroadcasting.my